TRANSPORT DOSIMETER

- During transportation and stroge of dosimeters, background radiation level shall be followed via transport dosimeter. Thus, Transport dosimeters is sent together with other dosimeters to give information about only occupational dose of radiation personals/workers.

In every period, dose value which is measured by transport dosimeter subtracted to dose value which is measured by personal/worker dosimeter.

Do not use the transport dosimeters for any other purpose.
Do not stroge transport dosimeters in radiation field.
Do not use transport dosimeters as personal dosimeter.

Transport dosimeters shall be sent back together with other dosimeters to RADAT Dosimetry Lab after every period.

If you have loss or any difficulty returning all of the dosemeters

from the wear period in one shipment, RADAT Dosimetry Lab. can

supply extra controls with your account at extra charge

For your questions and suggestions, you can reach our dosimetry service.

Taşpınar Mah. 2870 Sok. No:1 İncek-Gölbaşı/ANKARA Ph: 0(312) 447 3538 Fax: 0(312) 447 16 28 E-mail: info@radat.com.tr Web site: www.radat.com.tr